



Product Bulletin: PB-PCI-X Cards-1106

Announcing the Availability of X1047B-R6, X1047B-R6-C, X2052A-R6, and X2052A-R6-C PCI-X Cards

Revision History

04-December-06 – Updated the title with the list of cards.

02-February-07 – Updated What's New section

06-June-07 – Added X1047B-R6-C and X2052A-R5-C

24-October-08 – Added support on FAS6000 for X1047B

Proprietary and Confidential. Restricted to NetApp employees and channel partners, each of whom is under NDA obligations. This document may not be shared with customers without prior written permission from NetApp. © Copyright 2008 NetApp Inc. All rights reserved.

This PRODUCT bulletin informs NetApp sales and NetApp partners about new or changed NetApp™ products or services.

1. Summary
2. What's New?
3. Sales Tools
4. Customer-Ready Tools
5. System Requirements
6. Product Information
7. Regulatory Compliance
8. Warranty and Service
9. Additional Information

1. Summary

X1047B-R6, X1047B-R6-C, X2052A-R6, and X2052A-R6-C PCI-X Cards

This product bulletin announces the following cards in Add Parts with the November 2008 release and their planned availability as configured cards in the February 2009 release:

- The **X1047B-R6** card is a RoHS-compliant quad-port copper (RJ-45) PCI-X Network Interface Card (NIC).
 - Supported on FAS6000/A, FAS3020/A, FAS3050/A, V3020/A, V3050/A, and V6000/A series platforms (not FAS3070/A or V3070/A series).
- The **X2052A-R6** is a RoHS-compliant quad-port FC Initiator PCI-X HBA for use with either disk or tape.
 - Supported on FAS3020/A and FAS3050/A series platforms except for Fabric MetroCluster (not supported on V-Series or FAS3070/A series).

2. What's New?

The X1047B-R6 card is a replacement for the X1047-R5 card for FAS3020/A, FAS3050/A, V3020/A, and V3050/A series only. The FAS980/C will continue to use the X1047-R5.

The X1047B-R6 card is a replacement for the X1007A-R5 card on the FAS6000/A series only.

The X2052A-R6 is a new card that enables customers to use fewer slots to reach the desired number of FC ports. It also allows pairs of ports to be attached to tape SANs, so customers do not need to purchase a dedicated tape FC HBA.

3. Sales Tools (Sales Guides, Training Presentations, SE Presentations)

N/A

4. Customer-Ready Tools (Customer Presentations, Datasheets)

N/A

5. System Requirements

Data ONTAP

For X1047B-R6 7.0.6, 7.1.2, 7.2.1, 10.0.1 and later

For FAS6000 only X1047-B-R6 7.2.6 and 7.3.1

For X2052A-R5 7.1.2, 7.2.1, and later

Card Part Number	FAS6000/A	FAS3020/A	FAS3050/A	FAS3050A-GX
X1047B-R6	X	X	X	X
X2052A-R6		X	X	X

6. Product Information

Starting in the November release of the Quote Tool, these cards are available for customers running

the following versions of Data ONTAP®:

Part Number	Description	Discount Category	Supported Data ONTAP
X1047B-R6	NIC,4-Port,GbE,Copper,PCI-X,R6	A	7.0.6; 7.1.2; 7.2.1; and 10.0.1 FAS6000 only: 7.2.6 and 7.3.1
X2052A-R5	HBA,FC,4-Port,4Gb,Disk,PCI-X,R5	A	7.1.2 and 7.2.1
X1047B-R6-C	NIC,4-Port,GbE,Copper,PCI-X,R6	A	7.0.6; 7.1.2; 7.2.1; and 10.0.1
X2052A-R5-C	HBA,FC,4-Port,4Gb,Disk,PCI-X,R5	A	7.1.2 and 7.2.1

7. Regulatory Compliance

Products need to be validated against the NetApp Safety/EMI Regulatory Compliance List prior to order submission. This is required to ensure that products are being sold only in the countries in which NetApp has received regulatory compliance certification.

8. Warranty and Service

Standard three-year warranty period starts and ends with the warranty of the platform the card is plugged into.

9. Additional Information

Contact Information: Please contact your NetApp sales or channel partner representative with questions concerning this bulletin.



© 2008 NetApp | Subscriptions | Service and Support
495 E. Java Drive, Sunnyvale, CA 94089 USA

© 2008 NetApp. All rights reserved. Specifications are subject to change without notice. NetApp, the NetApp logo, Go further, faster, and NOW are trademarks or registered trademarks of NetApp, Inc. in the United States and/or other countries. All other brands or products are trademarks or registered trademarks of their respective holders and should be treated as such.