



Product Bulletin

Power Cable Transition from X1558A to X800-42U for Systems in Cabinets

Revision History

25 November 2008

Proprietary and confidential. Restricted to NetApp employees and channel partners, each of whom is under NDA obligations. This document may not be shared with customers without prior written permission from NetApp. © Copyright 2008 NetApp, Inc. All rights reserved.

This product bulletin informs NetApp sales and NetApp partners about new or changed NetApp® products or services.

1. Summary
2. What's New?
3. Sales Tools
4. Customer-Ready Tools
5. System Requirements
6. Product Information
7. Regulatory Compliance
8. Warranty and Service
9. Additional Information

1. Summary

Power Cable Transition from X1558A to X800-42U for Systems in Cabinets

Starting with the December 2008 release of eConfigurator in CE/PE, the 27" X800-42U internal power cord for NetApp system cabinets will be output for configured with FAS2000, 3000, 3100, 6000, SA, and VTL platforms and NetApp Select systems. It is a replacement for X1558A where applicable. In the February 2009 release of eConfigurator in CE/PE, all configurations will output the X800-42U part number.

The 48" X1558A power cord will remain in the price list. It is required in cases where the power outlet on a switch is facing the front of the cabinet.

2. What's New?

Not applicable.

3. Sales Tools (Sales Guides, Training Presentations, SE Presentations)

Not applicable.

4. Customer-Ready Tools (Customer Presentations, Datasheets)

Not applicable.

5. System Requirements

Not applicable.

6. Product Information

Not applicable.

7. Regulatory Compliance

Products need to be validated against the NetApp Safety/EMI Regulatory Compliance List prior to order submission. This is required to make sure that products are being sold only in the countries in which NetApp has received regulatory compliance certification.

8. Warranty and Service

Not applicable.

9. Additional Information

Contact information: Please contact your NetApp sales or channel partner representative with questions concerning this bulletin.

Go further, faster™

© 2008 NetApp | Subscriptions | Service and Support
495 E. Java Drive, Sunnyvale, CA 94089 USA